
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-143	Smoke	11/18/2008	ADS/TM	S110O1009MH	Dry	Yes	1,321.66

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11QQ1029G1	S11QQ1029MH	S11QQ1026MH	304.5947	8
S11QQ1026G1	S11QQ1026MH	S11QQ1021MH	203.8861	8
S11QQ1021G1	S11QQ1021MH	S11QQ1009MH	180.3119	8
S11QQ1009G1	S11QQ1009MH	S110O1009MH	312.5802	8
S110O1009G1	S110O1009MH	S110O1026MH	201.0408	8
S110O1026G1	S110O1026MH	S110O1005MH	119.2449	8

Observations & Photos

Obs_ID S1028-143-OB01

Address 2900 Oakley Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ1009MH

Comments Smoke from cleanout in front yard. 2900 Oakley Ave.



Picture \S1028-143-OB01-P01.jpg

Comments Front of house, 2900 Oakley Ave.

Obs_ID S1028-143-OB02

Address 2906 Oakley Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11QQ1009MH

Comments Smoke from cleanout in front yard. 2906 Oakley Ave.



Picture \S1028-143-OB02-P01.jpg

Comments Front of house, 2906 Oakley Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-143	Smoke	11/18/2008	ADS/TM	S11001009MH	Dry	Yes	1,321.66

Obs_ID S1028-143-OB03

Address 2913 Oakley Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11001009MH

Comments Smoke from cleanout in front yard. 2913 Oakley Ave.



Picture \S1028-143-OB03-P01.jpg

Comments Front of house, 2913 Oakley Ave.

Obs_ID S1028-143-OB05

Address 2916 Oakley Ave


Status Public

Source Service Lateral

Location Curb

Nearest MH S11001009MH

Comments Smoke from service lateral along curb 5 ft. from water meter. 2916 Oakley Ave.



Picture \S1028-143-OB05-P01.jpg

Comments Front of house, 2916 Oakley Ave.

Obs_ID S1028-143-OB04

Address 2925 Oakley Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11001009MH

Comments Smoke from cleanout in front yard. 2925 Oakley Ave.



Picture \S1028-143-OB04-P01.jpg

Comments Front of house, 2925 Oakley Ave.

Obs_ID S1028-143-OB06

Address 2927 Oakley Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11001009MH

Comments Smoke from cleanout in front yard. 2927 Oakley Ave.



Picture \S1028-143-OB06-P01.jpg

Comments Front of house, 2927 Oakley Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-143	Smoke	11/18/2008	ADS/TM	S11001009MH	Dry	Yes	1,321.66

Obs_ID S1028-143-OB07

Address 2931 Oakley Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11001009MH

Comments Smoke from cleanout in front yard. 2931 Oakley Ave.



Picture \S1028-143-OB07-P01.jpg

Comments Front of house, 2931 Oakley Ave.

Obs_ID S1028-143-OB08

Address 3011 Oakley Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11001005MH

Comments Smoke from cleanout in front yard. 3011 Oakley Ave.



Picture \S1028-143-OB08-P01.jpg

Comments Front of house, 3011 Oakley Ave.